


# Synagogue in Olkieniki



### Description

A wooden synagogue located in Olkieniki, Lithuania. It was erected at the end of the 18th century by the Jewish community living in the area. It was destroyed during the first days of the occupation of Lithuania during World War II by the German Nazis in June 1941.

### Scientific Advisor

Igor Bajena, Piotr Kuroczyński

### Modelling

Milena Micun, Wiktoria Piasta

### Cooperation Partnership



Warsaw University of Technology, University of Bologne, Hochschule Mainz

### Used Software

ArchiCAD


## Geo-coordinates

Latitude 54.358941   Longitude 24.841663



## Decisions

Truss Roofing



Working State: Final

Argumentation

Reconstruction

Sources

No reconstructions assigned

No sources assigned

## Decisions

First floor roofs



Working State: Final


Argumentation

Reconstruction



**Fig. 53** 2\_first floor roofing\_3D view.jpg

Sources




**Fig. 1** IS\_PAN\_RP799\_Olkieniki




**Fig. 12** 528. Olkieniki. View from west



**Fig. 13 529. Olkieniki. View from the south-west**



**Fig. 5 IS\_PAN\_RP12706\_Olkieniki**




**Fig. 6 533. Olkieniki. Section looking towards the east wall**

Working State: Work in progress


Argumentation

Reconstruction


Sources




**Fig. 24** First floor roofing\_3D view



**Fig. 1** IS\_PAN\_RP799\_Olkieniki



**Fig. 5** IS\_PAN\_RP12706\_Olkieniki



**Fig. 6** 533. Olkieniki. Section looking towards the east wall



**Fig. 12** 528. Olkieniki. View from west



**Fig. 13** 529. Olkieniki. View from the south-west

# Decisions

Main hall roof




Working State: Final

Argumentation

Reconstruction

Sources




**Fig. 49** 2\_main hall roof\_3D view.jpg




**Fig. 50** 2\_main hall roof\_front view.jpg




**Fig. 51** 2\_main hall roof\_side view.jpg



**Fig. 1** IS\_PAN\_RP799\_Olkieniki



**Fig. 4** IS\_PAN\_RP798\_Olkieniki



**Fig. 6** 533. Olkieniki. Section looking towards the east wall



**Fig. 12** 528. Olkieniki. View from west



**Fig. 13** 529. Olkieniki. View from the south-west




**Fig. 14** 532. Olkieniki. View from the east

Working State: Work in progress


Argumentation

Reconstruction


Sources




**Fig. 20** Main hall roof\_3D view



**Fig. 21** Main hall roof\_front view




**Fig. 1** IS\_PAN\_RP799\_Olkieniki





**Fig. 22** Main hall roof\_side view



**Fig. 6** 533. Olkieniki. Section looking towards the east wall



**Fig. 12** 528. Olkieniki. View from west



**Fig. 13** 529. Olkieniki. View from the south-west



**Fig. 14** 532. Olkieniki. View from the east

## Decisions



Load-bearing walls (main hall)

Working State: Final

Argumentation

Reconstruction


Sources



**Fig. 56** 2\_section\_with south wall in view.jpg



**Fig. 57** 2\_section\_with west wall in view.jpg



**Fig. 6** 533. Olkieniki. Section looking towards the east wall



**Fig. 11 177,178. Olkieniki, Bimah, before 1939**



**Fig. 14 532. Olkieniki. View from the east**

## Decisions


Load-bearing walls (vestibule)

Working State: Final


Argumentation

Reconstruction

Sources




**Fig. 56** 2\_section\_with south wall in view.jpg



**Fig. 5** IS\_PAN\_RP12706\_Olkieniki

**Fig. 57** 2\_section\_with west wall in view.jpg



**Fig. 2 IS\_PAN\_RP796\_Olkieniki**

# Decisions

Columns





Working State: Work in progress


Argumentation

Reconstruction

Sources



**Fig. 4 IS\_PAN\_RP798\_Olkieniki**



**Fig. 5 IS\_PAN\_RP12706\_Olkieniki**

**Fig. 30** Column




**Fig. 8** 74. Olkieniki. Interior of the cupola



**Fig. 11** 177,178. Olkieniki, Bimah, before 1939

Biforate windows





Working State: Final

Argumentation


Reconstruction

Sources



**Fig. 6** 533. Olkieniki. Section looking towards the east wall

**Fig. 34** biforate windows.jpg



**Fig. 47** biforate windows\_2.jpg



**Fig. 9 127.** Olkieniki. Holy Ark, the upper section



**Fig. 14 532.** Olkieniki. View from the east

## Decisions


Round windows




Working State: Final

Argumentation

Reconstruction



Sources



**Fig. 1** IS\_PAN\_RP799\_Olkieniki

**Fig. 58** 2\_round window\_front facade.jpg




**Fig. 12** 528. Olkieniki. View from west

Working State: Work in progress


Argumentation

Reconstruction

Sources



**Fig. 32** Round window



**Fig. 1 IS\_PAN\_RP799\_Olkieniki**



**Fig. 12 528. Olkieniki. View from west**

Rectangular windows

Working State: Final


Argumentation

Reconstruction

Sources



**Fig. 36** Rectangular windows



**Fig. 6** 533. Olkieniki. Section looking towards the east wall



**Fig. 14** 532. Olkieniki. View from the east

# Decisions

Doors




Working State: Final


Argumentation

Reconstruction


Sources




**Fig. 37** Front door and other doors



**Fig. 1** IS\_PAN\_RP799\_Olkieniki



**Fig. 4** IS\_PAN\_RP798\_Olkieniki



**Fig. 5 IS\_PAN\_RP12706\_Olkieniki**



**Fig. 12 528. Olkieniki. View from west**

# Decisions

Stairs

Working State: Final


Argumentation

Reconstruction



**Fig. 53** 2\_first floor roofing\_3D view.jpg


Sources




**Fig. 1** IS\_PAN\_RP799\_Olkieniki



**Fig. 57** 2\_section\_with west wall in view.jpg



**Fig. 2** IS\_PAN\_RP796\_Olkieniki



**Fig. 5 IS\_PAN\_RP12706\_Olkieniki**

# Decisions


Squinches



Working State: Final


Argumentation

Reconstruction




**Fig. 59** 2\_squinches\_3D view.jpg

Sources



**Fig. 4** IS\_PAN\_RP798\_Olkieniki



**Fig. 6** 533. Olkieniki. Section looking towards the east wall




**Fig. 10 128. Olkieniki. Holy Ark, the lower section**


## Working State: Work in progress

### Argumentation

### Reconstruction




### Sources



**Fig. 41** Squinches\_3D view

**Fig. 4** IS\_PAN\_RP798\_Olkieniki



**Fig. 6** 533. Olkieniki. Section looking towards the east wall



**Fig. 10** 128. Olkieniki. Holy Ark, the lower section

Balustrades and railings



Working State: Final


Argumentation

Reconstruction



**Fig. 42** Balustrades and railings

Sources



**Fig. 5** IS\_PAN\_RP12706\_Olkieniki



**Fig. 8** 74. Olkieniki. Interior of the cupola

Friezes

Working State: Final


Argumentation

Reconstruction



**Fig. 60** 2\_Friezes.jpg

Sources



**Fig. 1** IS\_PAN\_RP799\_Olkieniki



**Fig. 12** 528. Olkieniki. View from west




**Fig. 14** 532. Olkieniki. View from the east

Working State: Work in progress


Argumentation

Reconstruction

Sources



**Fig. 45** Friezes



**Fig. 1** IS\_PAN\_RP799\_Olkieniki




**Fig. 12** 528. Olkieniki. View from west



**Fig. 13** 529. Olkieniki. View from the south-west


Holy Ark




Working State: Work in progress

Argumentation


Reconstruction



Sources



**Fig. 5 IS\_PAN\_RP12706\_Olkieniki**



**Fig. 6** 533. Olkieniki. Section looking towards the east wall


**Fig. 39** Simplified Holy Ark




**Fig. 9** 127. Olkieniki. Holy Ark, the upper section




**Fig. 10 128.** Olkieniki. Holy Ark, the lower section




**Fig. 17** Truss roofing\_front view




**Fig. 18** Truss roofing\_side view




**Fig. 20** Main hall roof\_3D view




**Fig. 21** Main hall roof\_front view




**Fig. 22** Main hall roof\_side view




**Fig. 24** First floor roofing\_3D view




**Fig. 26** Vault\_view




**Fig. 27** section\_with south wall in view.jpg




**Fig. 28** section\_with west wall in view.jpg



**Fig. 30** Column




**Fig. 32** Round window




**Fig. 34** biforate windows.jpg




**Fig. 36** Rectangular windows



**Fig. 37** Front door and other doors




**Fig. 39** Simplified Holy Ark




**Fig. 41** Squinches\_3D view



**Fig. 42** Balustrades and railings



**Fig. 45** Friezes



**Fig. 47** biforate windows\_2.jpg




**Fig. 49** 2\_main hall roof\_3D view.jpg




**Fig. 50** 2\_main hall roof\_front view.jpg



**Fig. 51** 2\_main hall roof\_side view.jpg



**Fig. 53** 2\_first floor roofing\_3D view.jpg




**Fig. 54** 2\_vault\_view.jpg




**Fig. 55** 2\_main hall roof\_3D view\_section.jpg




**Fig. 56** 2\_section\_with south wall in view.jpg



**Fig. 57** 2\_section\_with west wall in view.jpg




**Fig. 58** 2\_round window\_front facade.jpg




**Fig. 59** 2\_squinches\_3D view.jpg



**Fig. 60** 2\_Friezes.jpg



**Fig. 62** Olkienniki\_23.06.dae



**Fig. 1 IS\_PAN\_RP799\_Olkieniki**

**Type** Drawn Reconstruction

**Used in:**

**Description** Front (west) elevation

Roof

**Author** Bronisław Żywno

**Archive** Instytut Sztuki PAN

**Signature** IS\_PAN\_RP799\_Olkieniki


Windows

**Copyright** IN COPYRIGHT - EDUCATIONAL  
USE PERMITTED

Doors


Stairs

Decorative elements




**Fig. 2 IS\_PAN\_RP796\_Olkieniki**

<b>Type</b>	Drawn Reconstruction	<b>Used in:</b>
<b>Description</b>	Floor plan	Walls
<b>Author</b>	Bronisław Żywno	
<b>Archive</b>	Instytut Sztuki PAN	Stairs
<b>Signature</b>	IS_PAN_RP796_Olkieniki	
<b>Copyright</b>	IN COPYRIGHT - EDUCATIONAL USE PERMITTED	



**Fig. 3 IS\_PAN\_RP797\_Olkieniki**

<b>Type</b>	Drawn Reconstruction	<b>Used in:</b>
<b>Description</b>	Vault plan	Roof
<b>Author</b>	Bronisław Żywno	
<b>Archive</b>	Instytut Sztuki PAN	Ceiling
<b>Signature</b>	IS_PAN_RP797_Olkieniki	
<b>Copyright</b>	IN COPYRIGHT - EDUCATIONAL USE PERMITTED	



**Fig. 4 IS\_PAN\_RP798\_Olkieniki**

**Type** Drawn Reconstruction

**Used in:**

**Description** Cross-section with the northern wall in view

Roof

**Author** Bronisław Żywno

**Archive** Instytut Sztuki PAN

Walls


**Signature** IS\_PAN\_RP797\_Olkieniki

**Copyright** IN COPYRIGHT - EDUCATIONAL  
USE PERMITTED

Posts

Doors

Decorative elements



**Fig. 5 IS\_PAN\_RP12706\_Olkieniki**

**Type** Drawn Reconstruction

**Used in:**

**Description** Perspective cross-section with the northern wall in view

Roof

**Author** Maciej Piechotka

Ceiling

**Archive** Instytut Sztuki PAN

Walls

**Signature** IS\_PAN\_RP12706\_Olkieniki

Posts


**Copyright** IN COPYRIGHT - EDUCATIONAL USE PERMITTED

Doors

Stairs

Decorative elements

Religious elements



**Fig. 6** 533. Olkieniki. Section looking towards the east wall

**Type** Drawn Reconstruction      **Used in:**

**Description** Transverse section looking towards the east wall; drawn by

W. Olkowski on the basis of measurements ZAP and photographs.

**Author** Wojciech Olkowski      **Used in:** Walls

**Archive** Zakład Architektury Polskiej  
WAPW      **Used in:** Windows

**Signature**

**Copyright** IN COPYRIGHT - EDUCATIONAL USE PERMITTED      **Used in:** Decorative elements

Religious elements



**Fig. 7 536.** Olkieniki. Interior of the cupola and the bimah canopy

**Type** Photograph

**Used in:**

**Description** Interior of the cupola and the bimah canopy, before 1939

Roof

**Author** S. Zajczyk

Ceiling

**Archive** Instytut Sztuki PAN

**Signature**

**Copyright** IN COPYRIGHT - EDUCATIONAL  
USE PERMITTED



**Fig. 8** 74. Olkieniki. Interior of the cupola

**Type** Photograph

**Used in:**

**Description** Interior of the cupola, before  
1939

Ceiling

Posts

**Author** S. Zajczyk

**Archive** Instytut Sztuki PAN

Decorative elements

**Signature**

**Copyright** IN COPYRIGHT - EDUCATIONAL  
USE PERMITTED



**Fig. 9** 127. Olkieniki. Holy Ark, the upper section

**Type** Photograph

**Used in:**

**Description** Holy Ark, the upper section  
before 1939

Windows

**Author** S. Zajczyk

Religious elements

**Archive** Instytut Sztuki PAN

**Signature**

**Copyright** IN COPYRIGHT - EDUCATIONAL  
USE PERMITTED



**Fig. 10 128.** Olkieniki. Holy Ark, the lower section

**Type** Photograph

**Used in:**

**Description** Holy Ark, the lower section  
before 1939

Decorative elements

**Author** S. Zajczyk

Religious elements

**Archive** Instytut Sztuki PAN

**Signature**

**Copyright** IN COPYRIGHT - EDUCATIONAL  
USE PERMITTED



**Fig. 11 177,178. Olkieniki, Bimah, before 1939**

**Type** Photograph

**Used in:**

**Description** Canopy of the bimah and entrance to the bimah

Ceiling

**Author** S. Zajczyk


Walls

**Archive** Instytut Sztuki PAN

Posts

**Signature**

**Copyright** IN COPYRIGHT - EDUCATIONAL  
USE PERMITTED



**Fig. 12 528. Olkieniki. View from west**

**Type** Photograph

**Used in:**

**Description** View from west

Roof

**Author** H. Struck

**Archive** Instytut Sztuki PAN

**Signature**

Windows

**Copyright** IN COPYRIGHT - EDUCATIONAL  
USE PERMITTED

Doors

Decorative elements



**Fig. 13 529.** Olkieniki. View from the south-west

**Type** Photograph

**Used in:**

**Description** View from the south-west,  
before 1939

Roof

**Author** S. Zajczyk

**Archive** Instytut Sztuki PAN

Decorative elements

**Signature**

**Copyright** IN COPYRIGHT - EDUCATIONAL  
USE PERMITTED



**Fig. 14** 532. Olkieniki. View from the east

**Type** Photograph

**Used in:**

**Description** View from the east, before 1939

Roof

**Author** S. Zajczyk

**Archive** Instytut Sztuki PAN


Walls

**Signature**

**Copyright** IN COPYRIGHT - EDUCATIONAL  
USE PERMITTED


Windows

Decorative elements




**Fig. 16** Truss Roofing

Type	Used in:
<b>Description</b>	
<b>Author</b>	
<b>Archive</b>	
<b>Signature</b>	
<b>Copyright</b>	



**Fig. 19** Main hall roof

Type	Used in:
Description	
Author	
Archive	
Signature	
Copyright	



**Fig. 23** Pitched Roof

Type	Used in:


**Description**

**Author**

**Archive**

**Signature**

**Copyright**



**Fig. 25 Vault**

**Type**

**Used in:**


**Description**

**Author**

**Archive**

**Signature**

**Copyright**




**Fig. 29** Columns

Type	Used in:
Description	
Author	
Archive	
Signature	
Copyright	




**Fig. 33** Round windows

Type	Used in:
<b>Description</b>	
<b>Author</b>	
<b>Archive</b>	
<b>Signature</b>	
<b>Copyright</b>	




**Fig. 35** Biforate windows

Type	Used in:
Description	
Author	
Archive	
Signature	
Copyright	




**Fig. 38** Doors

Type	Used in:
Description	
Author	
Archive	
Signature	
Copyright	



**Fig. 40** Holy Ark

Type	Used in:
Description	
Author	
Archive	
Signature	
Copyright	



**Fig. 43** Squinches

Type	Used in:
Description	
Author	
Archive	
Signature	
Copyright	



**Fig. 44** Balustrades and railings

Type	Used in:
<b>Description</b>	
<b>Author</b>	
<b>Archive</b>	
<b>Signature</b>	
<b>Copyright</b>	




**Fig. 46** Friezes

Type	Used in:
<b>Description</b>	
<b>Author</b>	
<b>Archive</b>	

**Signature**

**Copyright**



**Fig. 52** Main hall roof

**Type**

**Used in:**

**Description**

**Author**

**Archive**

**Signature**

**Copyright**